

Pressure Conversion Chart



To convert pressure from one unit to another:

1. Start at column heading with units to convert from.
2. Move down the same column to number "1".
3. Move across this row to the column with units heading you are converting to.
4. Multiply the number in this cell with the value you are converting from to get the new value in converted units.

psi	atms.	inch WC	mm WC	cm WC	oz/in ²	Kg/cm ²	inch Hg	mm Hg	cm Hg	mbar	bar	Pa (N/m ²)	KPa	MPa
1	0.0681	27.71	703.8	70.38	16	0.0704	2.036	51.715	5.17	68.95	0.0689	6,895	6.895	0.0069
14.7	1	407.2	10,343	1,034.30	235.1	1.033	29.92	760	76	1013	1.013	101,325	101.3	0.1013
0.0361	0.00246	1	25.4	2.54	0.5775	0.00254	0.0735	1.866	0.187	2.488	0.00249	248.8	0.249	0.00025
0.001421	0.000097	0.0394	1	0.1	0.0227	0.0001	0.00289	0.0735	0.00735	0.098	0.000098	9.8	0.0098	0.00001
0.01421	0.000967	0.3937	10	1	0.227	0.001	0.0289	0.735	0.0735	0.98	0.00098	98	0.098	0.0001
0.0625	0.00425	1.732	43.986	4.4	1	0.0044	0.1273	3.232	0.3232	4.31	0.00431	431	0.431	0.00043
14.22	0.968	394.1	10001	1000.1	227.6	1	28.96	735.6	73.56	980.7	0.981	98,067	98.07	0.0981
0.4912	0.03342	13.61	345.7	34.57	7.858	0.0345	1	25.4	2.54	33.86	0.0339	3,386	3.386	0.00339
0.01934	0.001316	0.536	13.61	1.361	0.31	0.00136	0.0394	1	0.1	1.333	0.001333	133.3	0.1333	0.000133
0.1934	0.01316	5.358	136.1	13.61	3.1	0.0136	0.394	10	1	13.33	0.01333	1,333	1.333	0.00133
0.0145	0.000987	0.4012	10.21	1.021	0.2321	0.00102	0.0295	0.75	0.075	1	0.001	100	0.1	0.0001
14.504	0.987	401.9	10,210	1,021	232.1	1.02	29.53	750	75	1,000	1	100,000	100	0.1
0.000145	0.00001	0.00402	0.102	0.0102	0.00232	0.00001	0.000295	0.0075	0.00075	0.01	0.00001	1	0.001	0.000001
0.14504	0.00987	4.019	102.07	10.207	2.321	0.0102	0.295	7.5	0.75	10	0.01	1,000	1	0.001
145.04	9.869	4019	102,074	10,207	2321	10.2	295.3	7500	750	10,000	10	1,000,000	1,000	1